

# NATF Redacted Operating Experience Report

## Conductor Broke When Increasing Tension

### [About NATF Redacted Operating Experience \(OE\) Reports](#)

North American Transmission Forum (NATF) operating experience reports highlight positive or negative transmission (reliability or resiliency) experiences worth sharing for learning opportunities or potential trending. The overall goal is to help each other learn without experiencing the same issues first-hand. This sharing originates confidentially within the NATF membership.

Redacted operating experience reports are posted on the NATF public website to allow the NATF and its members to more broadly share information, especially safety-related alerts and learnings, with contractors and other utilities to benefit the industry at large.

The NATF member company that submitted the initial restricted distribution OE report for this topic/event has approved the NATF to issue this redacted OE report.

### **Open Distribution**

Copyright © 2019 North American Transmission Forum. Not for sale or commercial use. All rights reserved.

### **Disclaimer**

This document was created by the North American Transmission Forum (NATF) to facilitate industry work to improve reliability and resiliency. The NATF reserves the right to make changes to the information contained herein without notice. No liability is assumed for any damages arising directly or indirectly by their use or application. The information provided in this document is provided on an “as is” basis. “North American Transmission Forum” and its associated logo are trademarks of NATF. Other product and brand names may be trademarks of their respective owners. This legend should not be removed from the document.

## Topic

Conductor Broke When Increasing Tension

## Description

A conductor broke while a line crew was working on a 161 kV line. No one was injured.

The crew's task was to add 18 inches of slack in a span that had increased in tension due to one of the structures slowly sliding or moving over the past 40+ years. The linemen had the wire held at the dead-end structure with a 6-ton hoist and conductor grip. The crew was about to disconnect the insulator string and add the hardware for 18 inches of slack when the conductor broke near the conductor grip. The linemen were working from a bucket truck and were not positioned in the bite of the conductor when it broke.

It was determined that the conductor tension was near its breaking strength and was too high to remove with traditional rigging methods. Our company decided to hire a specialized blasting company to implode the remaining conductors from the tower.





## Lessons Learned

1. Evaluate line equipment (e.g., hoists, clamps, come-along, etc.) to ensure rated capacities are correct.

## Actions Taken

1. Stopped work on the line and investigated the incident.
2. Worked with management to keep the circuit energized, which created heat in the conductor to reduce the actual tension until the lines could be replaced safely.
3. Coordinated with appropriate groups to ensure the remaining lines were safely removed.

## Extent of Condition

No additional lines were identified that were close to this type of tensile strength.